

PENANGANAN MUAT PALM KERNEL EXPELLER (PKE)

MV. VIANCA DI PELABUHAN DUMAI

Nama Taruna : Amirul Amin

NIT : 8303221260

Dosen Pembimbing : Nur Rahmani M.Si

Abstrak

PT Pelayaran Cahya Papua merupakan salah satu perusahaan jasa keagenan yang mengageni kapal yang mengangkut hasil produk turunan minyak kelapa sawit seperti CPO (crude palm oil) dan PKE (Palm Kernel Expeller). Adapun permasalahan dan tujuan pada penelitian ini adalah untuk mengetahui penanganan muat PKE di MV. Vianca di pelabuhan dumai dan guna mengetahui faktor yang menghambat penanganan muat PKE. Penelitian ini menggunakan teknik pengumpulan data yaitu menggunakan data melalui observasi, wawancara dan dokumentasi adapun hasil penelitian ini menggunakan teknik analisis data kualitatif secara deskriptif. Penanganan muat PKE di MV. Vianca di Pelabuhan Dumai dilakukan dengan menggunakan alat muat conveyor yang dapat meningkatkan efisiensi dan produktivitas dalam proses penanganan muat PKE. Faktor yang menghambat penanganan PKE di MV. Vianca di Pelabuhan Dumai adalah, macetnya conveyor keterbatasan tenaga kerja, cuaca buruk, dan kesalahan pengaturan alat muat.

Kata Kunci : Penanganan, muat, Pelabuhan, Pengakutan,

HANDLING OF LOADING AND PALM KERNEL EXPLLER(PKE) MV. VIANCA IN DUMAI PORT

Cadet Of Name : Amirul Amin

NIT : 8303221260

Advisor 1 : Nur Rahmani M.Si.

Abstract

PT Pelayaran Cahya Papua is one of the agency service companies that agents ships that transport palm oil derivative products such as CPO (crude palm oil) and PKE (Palm Kernel Expeller). The problems and objectives of this study are to determine the handling of PKE loading on MV. Vianca at Dumai Port and to determine the factors that hinder the handling of PKE loading. This study uses data collection techniques that use data through observation, interviews and documentation while the results of this study use descriptive qualitative data analysis techniques. PKE loading handling on MV. Vianca at Dumai Port is carried out using a conveyor loading tool that can increase efficiency and productivity in the PKE loading handling process. Factors that hinder the handling of PKE on MV. Vianca at Dumai Port are, conveyor jams, limited labor, bad weather, and errors in loading equipment settings.

Keywords: Loading and handling, port, transportation